

Mastercam Software Extension





Table of Contents

- 1. Product Information
- 2. User Guide
- 3. Contact





Product Information

Product Name : Byte Automation for Mastercam

Product Description: Chains a Parasolid 3D Model using Mastercams API to create a toolpath.

Software Version : (For older versions of the software, please contact sales@theebyte.com)

Version : 1.0.0.1

Number Of Seats : 1

License Type : Perpetual

License Duration : Unlimited

License : Mill Entry, Mill 2D, Mill 3D, Router Entry, Router 2D, Router 3D.

Release Date : 05-22-2022





User Guide

Step 1.

Open Mastercam 2023 by either searching for it in the start menu or by using the Desktop shortcut.



Step 2.

Select the Byte Automation tab to view the main menu.



Step 3.

Select the Automatic Mill Toolpaths Manager Button to create the Automatic Mill Toolpaths Manager window.



Step 4.

Select the Automatic Mill Toolpaths Manager window's Tab from the Manager Pane area..

다 🖬 🖶 🔛 💓 (*	Mastercam Design 2023		- 🗆 ×
File Home Wireframe Surfaces Solids Model Prep Mesh Draft	fting Transform Art Machine View	Byte Automation	Standard 🔹 My Mastercam 🗏 🙆 🔺
Automatic Mill Advanced Mill Merge Importer Toolpaths Manager Toolpaths Manager Manager 10 Toolpaths Manager 6 Pool-UB Mindager 6 Pool-UB Mindager 6	Surfaces Stl To Solid Solid Extrude Factory Entity Factory Boolean Add Editor Boolean Add Clo	Sketch Plane On Mark All Fill Surface Voids Create	Wireframe Create Geometry Move Entities Surfaces On Solid To Zero
Automatic Mill Toolpaths Manager 🔹 🖲 🗙	🔓 🗽 AutoCursor - 📩 🍖	8 9 9 9 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Automatic Mill Tocipaths			
O Set Limit depth to True Length O Set Limit depth to AssemblyLength O Set Limit depth to AssemblyLengtl O Set Router Mode O Set Multiple Operations			E 0 0 0
Toolpaths Automatic Mill Toolpaths Manager	SECTION VIEW: OFF SELECTED ENTITIES: 0 X	: -510696 Y: 2.82442 Z: 0.00000 - 3D CPLANE: - TP	LANE: - WCS:





User Guide


Step 5.

Select a Solid to Create a Toolpath around.

C □ □ □ 	D:\Users\byte\Documents\My Mastercam 2023\Mastercam\Parts	(T.mcam* - Mastercam Design 2023	- 🗆 X
File Home Wireframe Surfaces Solids Model Prep	Mesh Drafting Transform Art Machine View	Byte Automation Standard	• My Mastercam 🖳 🔞 4
	. 🛆 🔺 🔳 🔳		
Automatic Mill Advanced Mill Merge Importer Excel Mill Script To	olpaths Stl To Surfaces Stl To Solid Solid Extrude Solid Ext		
Toolpaths Manager Toolpaths Manager Manager Toolpaths Manager Mana Docking Managers Ts Pop-Up Windows	ger Entity Factory Entity Factory Boolean Add Editor Boolean Ad	I Closed Surf Plane Factory C-Plane Surfaces Entity Factory on Surfaces Geometry Tools	On Solid To Zero
Automatic Mill Toolpaths Manager 🔹 🤹 🛪 Automatic Mill Toopaths	🔓 🏦 AutoCursor × 📩 🍾	₹8030@#+ ≣ + <mark>8</mark> ½Ø%	
B B App Manager		1	PØ
└ o 0125 EndMill Flat Metal Contour.n			
Pocket			M X
0125 EndMill Flat Metal Pocket.mc			
Settings Set limit donth to Elute Longth			
 Set Limit depth to Flute Length Set Limit depth to Tool Length 			
 Set Limit depth to AssemblyLengtl 			<u> </u>
O Set Router Mode Set Multiple Operations			6
4 •			
Toolpaths Automatic Mill Toolpaths Manager			0.7125 m
Company Parentine min roopans manager	SECTION VIEW: OFF SELECTED ENTITIES: 1 X: -6.272	16 Y: 2.83184 Z: 0.00000 3D CPLANE: Top TPLANE: Top WCS:	тор - Ф.Ф.Ф. 🔍 🎒 🥝 .

Step 6.

Select the text of an operation to import and chain to the selected solid(s).









User Guide

The tool will pass on the inside and outside of the part performing the number of rough & finish passes set in the defaults file.



Additional operation files to import can be added to the folder shown below.







Contact

Email: sales@theebyte.com

Website: www.theebyte.com

Business Partner



